

PML Chute Packing Space Requirements

Approximate Linear Inches of Tubing Required to Store This Chute

Chute Size >	STREAMER	X-FORM	PAR-18	PAR-24	PAR-30	PAR-36	PAR-48	PAR-54	PAR-60	PAR-72	PAR-84	PAR-96	PAR-120
Tube Diameter													
2.1"	3.0	5.0	3.0	4.0	4.0	6.5	8.0	n/a	n/a	n/a	n/a	n/a	n/a
2.5"	2.0	5.0	2.0	3.5	3.0	5.0	6.5	9.0	n/a	n/a	n/a	n/a	n/a
3"	2.0	4.0	1.5	2.5	2.5	5.0	5.0	7.0	n/a	n/a	n/a	n/a	n/a
3.9"	1.0	3.5	1.0	2.0	1.5	3.0	4.0	4.0	5.5	12.0	14.0	15.0	18.0
6"	1.0	2.0	< 1	1.0	< 1	2.5	2.0	3.0	3.0	3.5	4.0	4.5	6.0
7.5"	n/a	1.5	< 1	< 1	< 1	1.5	1.0	2.0	2.5	3.0	3.0	3.0	4.0
11.4"	n/a	< 1	< 1	< 1	< 1	< 1	< 1	1.5	1.5	1.5	2.0	2.0	3.0

PML Tubular Nylon Packing Space Requirements

Total TN In Use	10 feet			20 feet			30 feet		
TN Size >	3/8" (TN-0.375)	9/16" (TN-0.5625)	3/4" (TN-0.75)	3/8" (TN-0.375)	9/16" (TN-0.5625)	3/4" (TN-0.75)	3/8" (TN-0.375)	9/16" (TN-0.5625)	3/4" (TN-0.75)
Tube Diameter									
2.1"	2.0	4.0	4.0	4.0	8.0	8.0	6.0	12.0	12.0
2.5"	2.0	3.0	2.5	4.0	6.0	5.0	6.0	9.0	7.5
3"	1.5	3.0	2.0	3.0	6.0	4.0	4.5	9.0	6.0
3.9"	1.0	1.0	1.5	2.0	2.0	3.0	3.0	3.0	4.5
6"	0.5	0.5	1.0	1.0	1.0	2.0	1.5	1.5	3.0
7.5"	0.4	0.4	0.8	0.8	0.8	1.5	1.3	1.3	2.3
11.4"	0.4	0.4	0.5	0.8	0.8	1.0	1.3	1.3	1.5